## **Process Sheet**

**Drawing Name** 

: D3136-041

**Part Number** 

: D3136041

**Drawing Number Project Number**  : INSPECT

**Drawing Revision** 

: NIA : MA

Material

: THERMOFORMING

: HA

**Due Date** 

: 31/12/2007

Qty:

5 Um: Each



**Machine Or Operation:** Seq. #:

1.0

Description:

SMALL & MEDIUM FAB RESOURCE 1

SMALL FAB 1

Comment: SMALL & MEDIUM FAB RESOURCE 1

REMOVE FROM STOCK:

D3136-041 B/R23707

REMOVE WHITE PAPER PROTECTOR

INSPECT FOR SCRATCHES OR DEFECTS **DISCARD & INDICATE ANY SCRAP WINDOWS:**  B23709

RE-WRAP IN PLASTIC WRAP

07-12-24

2.0

QC5



INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

3.0 **PACKAGING**  PACKAGING RESOURCE #1





Comment: PACKAGING RESOURCE #1

RETURN TO STOCK USING ORIGINAL B/N

4.0

QC21

FINAL INSPECTION/W/O RELEASE



08/01

Job Completion



Comment: FINAL INSPECTION/W/O RELEASE

mi 2008/1/2

Page 1

Form: rprocess

Dart Aerospace I	space Ltd
------------------	-----------

W/O:		WORK ORDER CHANGES						
DATE	TE STEP PROCEDURE CHANGE		Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
7.12.					·			
			·					

NCR:	254	WORK ORDER NON-CONFORMANCE (NCR)								
DATE	OTED	Description of NC		Corrective Action Section B	Verification	Approval	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	Chief Eng	QC Inspector		
07-12-23	1.0	Qty 3 windows scrop, che to ma cle formations; in the windows.	Posicur	Scripe destray B23709	SAD A-12-2	7 1/12:27	Posiwir	MA:12-2-		
	:					-				
	\$									

NOTE: Date & initial all entries